TROUBLE SHOOTING GUIDE
BRAKES

PROBLEM	CAUSE	SOLUTION
#1 OVERHEATING OF BRAKES ON 86 SERIES TRACTORS (EARLY MODELS WITH OPEN CENTER HYDRAULICS) 786, 886, 986, 1086, 1486.	A. PLUGGED OR RESTRICTED ORIFICE.	A. INSTALL 830601 SUPERCHARGE ELIMINATION KIT AND OVERSIZE BRAKE LUBE ORIFICES.
#2 NO BRAKES WHEN TRACTOR IS FIRST STARTED.	A. BRAKE CHECK VALVE LEAKING.	A. FOR 06, 26, 56, 66, 68 SERIES TRACTORS, REPLACE CHECK VALVE IN MCV. FOR 86, 88 SERIES TRACTORS, REPLACE CHECK VALVE ON FIRE WALL.

IF YOU HAVE ANY PROBLEMS NOT LISTED IN THIS GUIDE,
PLEASE CALL AG PARTS, LTD. SERVICE DEPARTMENT FOR HELP.